



HCP Screening Audiometers from other Services and Government Agencies

Types of audiometers:

Benson Medical CCA-200 and CCA-200mini

Process for the annual calibration of HCP screening audiometers:

- Contact the Calibration Laboratory before sending audiometers in calibration.
- Ensure power to the audiometer is off before disconnecting it (and later reconnecting it after calibration).
- Securely pack and mail your audiometers to the Calibration Laboratory at NMCPHC in a durable box.
 - Include a completed form DD1149 in the box. Ensure that your command's name, mailing address, point of contact, telephone number, and email address are complete and accurate.
 - Send your audiometers to:
 - Navy and Marine Corps Public Health Center
Attn: Calibration Laboratory
620 John Paul Jones Circle, Bldg. 3, Suite 1100
Portsmouth, VA 23708
- Upon completion of calibration, your audiometers will be shipped back to you via USPS or FedEx, depending on your mailing address.
- Contact the Calibration Laboratory if you have any questions. Visit our website at <http://go.usa.gov/pZhw> for our contact information.